PRQ-LK2-A (U No. - Parts List)

U NUMBER	PART NUMBER	PAGE	NUMBER	•
U21	Cambion Component Header		5	
U31	74S74		2	
U41	74S241		2	
U51	899-5-R 180/390		1	
U61	74\$ 241		1	
U71	899-5-R180/390		1, 2	
U72	74\$32		4 Part	for Diagnostic
U81	74\$241		4	Option
U91	67\$376		2	
U92	74S20		2	
U101	74\$138		2	
U111	74S374		1	
U112	74S00	•	4 Part	for Diagnostic
U121	74S374		1	Option
U1 22	74S04		2	
U131	74LS374		3	
U141	74LS374		3	Parts for
U151	74S2 88		4	Diagnostic Option
U161	74S288		4	0703011
U180	74S04		2, 4	

PROPRIETARY INFORMATION
FOR USE IN MAINTENANCE
ONLY. NOT TO BE COPIED
OR DISCLOSED!

	Three	Rivers	Computer	7
5))	TONO. PARTS	1157	marph 1- LRI-A	_
77	Control of the Contro	"FFG-P.	-0408A 2 - 3	ز

PRQ-LK2-A BYPASS LIST

.01
2.2
.01
.01
2.2
.01
.01
2.2
.01
2.2
.01

NOTE: For all 2.2 bypass, the silkscreen dot indicates ground.

PROPRIETARY INFORMATION
FOR USE IN MAINTENANCE
ONLY, NOT TO BE COPIED
OR DISCLOSED!

7	Star Contra	Three	Rivers	Computer	
5))	FYFF	2 15		" Du (- / - " -	-7
	CHICKID ST. D.	23/30		AdATE MIL OF	3


PRQ-LK2-A (INVENTORY) PARTS LIST


JANTITY	NO. PINS	Vcc	G	WIDTH	PT. NO.	NAME	DESCRIPTION (U NO.)	PAGE NO.
1 3 1 2 *2 *2 1 *1 2	14 20 20 16 20 20 16 14 14	14 20 20 16 20 20 16 14 14	7 10 10 8 10 10 8 7 7	.300 .300 .300 .300 .300 .300 .300 .300	74S74 74S241 67S376 74S138 74S374 74LS374 74S288 74S20 74S00 74S04	Chip Chip Chip Chip Chip Chip Chip Chip	U31 U41, U61, U81 U91 U101 U111, U121 U131, U141 U151, U161 U92 U112	2 1, 2 2 2 1 3 4 2
*] *]	14	14 14 16	7 7 -	.300	74S32 702 - 3728-	Chip Chip Cambion Com-	U122, U180 U72	4
2	14	14	7	.300	01-03-00 899-5-R180/ 390 PRQ-PCB-	ponent Header Resistor	U21 U51, U71	5 1,2
2		-			WW2-B 107 YEL 107 BLK 3202	Board Ejector Nylon Washers	l Yellow, l Black	7
20	20				520 AG 37F2 PRQ-HDW- STF-A	Wire Wrapped Auget Sockets Card Stiffeners		
2 4 7	40		ini.		3432- 3005 ST821 A225 CY15C 103M	Bent Nail Wire Wrap Scotchflex 2.2 mf Capacitor .01 mf Capacitor	JA, JB C41, C91, C131, C169 C31, C61, C72,	-
3 2 1 4	8 1				3911390-A 3911310-1 1K RC07 GS4-7	WW Header WW Pin Resistor Stimpson Rivets Stimpson	C111, C112, C151, C179 2 Rows of 4 1 Pin U21 Header	
						Rivets		


^{*} The following parts are used for the diagnostic option and should not be used in a regular link card:

U131
UL41 PROPRIETARY INFORMATION UL151 PROPRIETARY INFORMATION
U161 FOR USE IN MAINTENANCE
UITE ONLY NOT TO BE COPIED
OR DISCLOSED!

	Three	Rivers	Computer	
হী)	THUENTURY PAR	#5 LIST	19/10-6-12-A 1-04098 - 3 - 3	긥










PROPRIETARY INFORMATION
FOR USE IN MAINTENANCE
ONLY. NOT TO BE COPIED
OR DISCLOSED!

=		Three	Rivers	Computer	
(5)	"" IO	ECHO		""" PR3-4K2-A	
79	CHECKIE BY	N 4-3-70 #	73-56-	\$321-B -43 0.	5



PROPRIETARY INFORMATION
FOR USE IN MAINTENANCE
ONLY, NOT TO BE COPIED
OR DISCLOSED!





PROPRIETARY INFORMATION
FOR USE IN MAINTENAMES
ONLY, NOT TO SECONED
OR DISCLOSED!

15		Three	Rivers	Computer
(3)	HEA			"" PFQ- LF2-A
	L /	10,20,00	PR Q-	-1-09-A-5 - 5